

FD

material.

mixing crystalline graphite particles with the solution;
refluxing the mixture;
filtering the mixture to obtain a powder; and
heat treating the powder at approximately 1000°C to obtain the active
